



(SP5500 pictured)

Firmware:

- SP4000 and SP65 version 5.12
- SP5500, SP6000, SP7000, and MG5050 version 4.92

Overview:

- New section restrictions added

The following sections/options have been added to the MG/SP Series V4.92/V5.12. They may not be included in any manuals, therefore use this document in conjunction with the programming guide to program your panel.

New Section Restrictions Added

When entering programming mode using a Maintenance Code, the following section restrictions have been added:

- [918] - IP module - IP reporting account 1
- [919] - IP module - IP reporting account 2
- [920] to [927] - PCS configuration
- [929] to [935] - IP receiver 1 configuration
- [936] to [942] - IP receiver 2 configuration
- [943] to [949] - IP receiver 3 configuration